

WARNING

**IT IS MOST IMPORTANT THAT THE
MOTOR AND PUMP ARE CHECKED
FOR ACCURATE ALIGNMENT AFTER THE
BASEPLATE HAS BEEN GROUDED
INTO FINAL POSITION**